



3D Scan to CAD (Reverse Engineering, Quality Assurance)




No 3D-data exist?

QA-Check (Compare)



„dumb“ triangulated Mesh becomes smart CAD (B-Rep)



Ok, 3D- scanning with a precision of $< 0.02\text{mm}$!

How it works:

- Send Photo with dimensions
- Let's talk
- Agree on a fixed price
- Send part or to be scanned onsite
- Wait for download-Link (< 5 Workdays)
- Receive part back
- Ready to manufacture!

web: www.phanos3d.com
email: info@phanos3d.com

DE: +49 (0)172-6725681
CH: +41 (0) 77-278 08 24